

# STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

JAMES B. HUNT JR.

P.O. BOX 25201. RALEIGH, N.C. 27611-5201

E. Norris Tolson - SECRETARY

GOVERNOR

February 9, 1999

N.C. Dept. of EHNR

Ms. Cindy Rintoul DWM - UST Section Winston-Salem Regional Office 585 Waughtown Street Winston-Salem, NC 27107

SUBJECT:

Underground Storage Tank (UST) Closure and Assessment Report

Former Polly Edwards Property Former Helen Carroll Property Former Jack Sillmon, Heirs Property

Dear Ms. Rintoul:

Please find attached a copy of the "UST Closure and Assessment Report" for the three above referenced properties. This report was prepared by ARCADIS Geraghty & Miller, Inc. (ARCADIS) for the NCDOT Geotechnical Unit/GeoEnvironmental Section. All the USTs were non-regulated heating oil or farm tanks discovered during the early stages of construction along Guilford College Road (SR 1546) in Greensboro, NC. No contaminated soils were encountered during closures activities at the Edwards or Carroll sites. At the Sillmon site, a small amount of contaminated soil was excavated and stockpiled onsite. We are currently in the process of having a soil disposal company properly dispose of this stockpile.

Should you require more information about the sites, please feel to contact me at (919) 250-4088.

Sincerely

Eugene Tarascio

Project Environmental Geologist

Geotechnical Unit/Geoenvironmental Section

ET

Attachment

# Underground Storage Tank Closure Assessment Report



DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS
GEOTECHNICAL UNIT

State Project No. 8.U492101 TIP No. (U-2524AA) Guilford College Road Right-of-Way Greensboro, Guilford County, North Carolina



January 1999

PREPARED FOR

Geotechnical Unit North Carolina Department of Transportation

Underground Storage Tank Closure Assessment Report

State Project No. 8.U492101 TIP No. (U-2524AA) Guilford College Road Right-of-Way Greensboro, Guilford County, North Carolina

Prepared for: Geotechnical Unit North Carolina Department of Transportation

Prepared by:
ARCADIS Geraghty & Miller, Inc.
2301 Rexwoods Drive
Suite 200
Raleigh
North Carolina 27607
Tel 919-782-5511
Fax 919-782-5905

Our Ref.: NC000541.0001

Date: January 1999

# UNDERGROUND STORAGE TANK CLOSURE ASSESSMENT REPORT

STATE PROJECT NO. 8.U492101
TIP NO. (U-2524AA)
GUILFORD COLLEGE ROAD RIGHT-OF-WAY
GREENSBORO, GUILFORD COUNTY
NORTH CAROLINA

January 1999

Prepared by ARCADIS GERAGHTY & MILLER, INC.

Robert J. Ellis Scientist/Geologist

James E. Shilliday, III, L.G. Senior Scientist/Department Manager

William H. Doucette, Jr., Ph.D., L.G.

Associate/Project Advisor

I. INTRODUCTION	1-1
1.1 Purpose	1-1
1.2 Site Description	1-1
2. FIELD ACTIVITIES	2-1
2.1 Underground and Aboveground Storage Tank Removals	2-1
2.2 Soil Excavation	2-2
2.3 UST Closure Sampling	2-2
2.4 Stockpile Sampling	2-3
2.5 Excavation Backfilling	2-4
3. ANALYTICAL RESULTS	3-1
3.1 UST Closure Sample Analytical Results	3-1
3.2 Stockpile Sample Analytical Results	3-1
4. CONCLUSIONS	4-1
5. REFERENCES	5-1
Tables	
2-1. Summary of Underground Storage Tank (UST) and Above Groun	d Storage

- 2-1. Summary of Underground Storage Tank (UST) and Above Ground Storage Tanks (AST) removed on January 5, 1999, Guilford College Road Right of Way, State Project No. 8.U492101(U-2524AA), Greensboro, North Carolina.
- 3-1. Summary of Soil Analytical Results for UST Closure Samples and Stockpile Samples Collected on January 5, 1999, UST Removals, Guilford College Road Right Of Way, State Project NO 8.U492101 (U-22524AA), Greensboro, North Carolina.

# **Figures**

- 1-1. Site Location.
- 1-2. Site Layout.
- 2-1. Excavation Pit, Stockpile and Soil Sampling Locations, Former Polly Edwards Property (parcel # 23).

- 2-2. Excavation Pit, Stockpile and Soil Sampling Locations, Former Jack Sillmon Heirs Property (parcel # 45).
- 2-3. Excavation Pit, Stockpile and Soil Sampling Locations, Former Helen Carroll Property (parcel # 961).

# **Appendices**

- A. Non-Hazardous Waste Material Manifests.
- B. Certificates of Disposal for USTs and ASTs.
- C. UST Closure Forms (UST-2) and UST Closure Reports (GW/UST-12).
- D. Laboratory Analytical Data Reports.

Underground Storage Tank Closure Assessment Report

INTRODUCTION

## 1. INTRODUCTION

ARCADIS Geraghty & Miller, Inc. is pleased to submit this Underground Storage Tank (UST) Closure Assessment Report to the North Carolina Department of Transportation (NCDOT), Geothechnical Unit.

### 1.1 Purpose

This report documents the permanent closures of three non-regulated USTs located within the Guilford College Road right of way, south of Greensboro, Guilford County, North Carolina. Approximate locations of the former USTs are shown on Figure 1-1. The former USTs were located on properties formerly owned by Mrs. Polly Edwards (parcel #23), Mrs. Helen Carroll (parcel #961), and the Mr. Jack Sillmon Heirs (parcel #45). The three USTs were closed by removal on January 5, 1999.

### 1.2 Site Description

Three abandoned USTs were discovered within the NCDOT right of way by NCDOT personnel during the early stages of road construction on Guilford College Road, Greensboro, Guilford County, North Carolina, State Project Number 8.U492101 (U2524-AA). The locations of the three USTs are shown on Figure 1-2. One former UST containing gasoline was removed from the property formerly owned by Mrs. Polly Edwards (parcel #23). The approximate location of this UST was 160 m west of the current Guilford College Road and 60 m north of Hickory Grove Road. A former home heating oil UST was removed from the property formerly owned by Mrs. Helen Carroll (parcel #961). The approximate location of this UST was 40 m northwest of the current intersection between Guilford College Road and Sapp Road. Another home heating oil UST plus three above ground storage tanks (ASTs) containing heating oil were encountered on the property formerly owned by the Mr. Jack Sillmon Heirs (parcel #45). The approximate location of this UST was 160 m west of the current Guilford College Road and 75 m north of Wendover Avenue.

Underground Storage Tank Closure Assessment Report

FIELD ACTIVITIES

# 2. FIELD ACTIVITIES

The procedures followed for the soil excavation, stockpiling, and sampling activities are presented in this section.

## 2.1 Underground and Aboveground Storage Tank Removals

The three abandoned USTs and the three ASTs were closed by removal on January 5, 1999. Tank removal and soil excavation services were subcontracted through Soil Solutions, Inc. (SSI) of Winston-Salem, North Carolina. A summary of former UST and AST owners, locations, volumes, dimensions, contents, and composition is provided in Table 2-1.

Notice of Intent: UST Permanent Closure or Change in Service Forms (Form UST-3) were not required to be filed for these tanks because they were considered non-regulated by the North Carolina Department of Environment and Natural Resources (NCDENR). All three USTs had capacities of less than 1,100 gallons and the contents (gasoline or home heating oil) were used for non-commercial purposes. All UST closure field activities were conducted in accordance with the NCDENR, Groundwater Section Guidelines For the Investigation and Remediation of Soils and Groundwater - Volume II (NCDENR, 1998a).

Prior to beginning the UST removals, liquid petroleum products and sludge materials contained within the USTs were removed using a vacuum truck and disposed of at HOH Corporation by SSI. Non-Hazardous waste material manifests are presented in Appendix A. Vapors were purged from the USTs using dry ice. Vapor concentrations within the USTs were monitored by SSI by placing a combustible gas indicator (CGI) probe in the fill opening. Readings of 10 percent or less of the lower explosive limit (LEL) were obtained before the tanks were considered safe for removal.

Soil overburden was removed and stockpiled by SSI using a backhoe/excavator at each UST location. ARCADIS Geraghty & Miller guided the excavation activities by visually inspecting and screening soil samples with an organic vapor meter (OVM). OVM readings (above 50 parts per million [ppm]) were used to segregate impacted soil from non-impacted soil. The PID was calibrated on at least a daily basis using a zero gas and a 100 part per million by volume (ppmv) isobutylene calibration gas.

The USTs removed from the former Polly Edwards and the Helen Carroll properties were inspected upon removal and appeared to be in good condition with no visible signs of damage of deterioration. The UST removed from the former Jack Sillmon

Underground Storage Tank Closure Assessment Report

FIELD ACTIVITIES

Heirs property was inspected upon removal and appeared to have small dents and cracks on the top portion of the tank. This apparently had allowed the tank to fill with infiltrating water over time. The side-walls and bottom of the UST appeared to be in good condition with no visible signs of damage. The three ASTs and the one UST from the Jack Sillmon property and the USTs from the other two properties were transported off-site by SSI and disposed of at Safeway Tank Disposal, Colfax, North Carolina.

Tank manifests were initiated upon removal from the ground and completed upon destruction of the tanks. The certificates of disposal for each of the tanks are provided in Appendix B. Copies of the UST Closure Forms (GW/UST-2) and UST Closure Reports (GW/UST-12) for these USTs are provided in Appendix C.

### 2.2 Soil Excavation

Minor surface contamination was noted in the soil overburden above the UST at the Jack Sillmon Heirs Property, apparently resulting from infiltrating water entering and overflowing the damaged tank. However, this soil was excavated and stockpiled during the removal of the UST and no further abatement was necessary at that location. Excavated soil (less than 3.8 cubic meters) that was suspected to be impacted was stockpiled on polyethylene sheeting near the excavation pits and within the NCDOT right-of-way. The stockpiled soil was covered with a polyethylene liner and contained on all sides with bails of straw. There was no indication of impacted soil above the USTs at the other two sites. However, the soil overburden at each of these sites (less than 3.8 cubic meters, at each site) was stockpiled following the same procedure described above.

After each of the three USTs were removed, visual observations and screening using the OVM indicated that no impacted soil was present in the bottom of the excavation pits. No excavation, in addition to the soil overburden, was necessary at any of the locations. Groundwater was not encountered during the UST removals.

### 2.3 UST Closure Sampling

A total of two soil samples were collected from each of the UST excavation pit bottoms on January 5, 1999. Samples from the Mrs. Polly Edwards property (parcel #23) on Hickory Grove Road were labeled HG-1, HG-2. Samples from the Mr. Jack Sillmon Heirs property (parcel #45) located off of Wendover Avenue were WA-1, WA-2. Mrs. Helen Carroll property (parcel #961) located off of Guilford College

Underground Storage Tank Closure Assessment Report

FIELD ACTIVITIES

Road were labeled GC-1, and GC-2. The excavation pit and soil sample locations for these properties are shown on Figures 2-1, 2-2, and 2-3, respectively.

The six closure soil samples (HG-1, HG-2, WA-1, WA-2, GC-1, and GC-2) were collected from the excavation bottoms. Soil samples were collected from the backhoe bucket using a stainless steel spoon. The samples were then packed on iced in a laboratory-provided sample cooler immediately after collection, and transported by ARCADIS Geraghty & Miller personnel directly to C&ET in Cary, North Carolina to be analyzed for high fraction hydrocarbons and low fraction hydrocarbons using USEPA Methods 3550 and 5030, respectively. A chain of custody record was provided with each cooler containing samples to maintain a record of personnel that had contact with the samples. The results of the soil analyses are discussed in Section 3.1.

### 2.4 Stockpile Sampling

The total volume of soil excavated and stockpiled was less than 4 cubic meters at each UST location. The NCDENR requires that one representative sample be collected for every 152.9 cubic meters of stockpiled soil. Therefore, one hand-augered soil boring was advanced within each stockpile for a total of three borings. Three discrete subsamples were collected from three depths at each of the boring locations. In each case sub-samples from these depths were labeled A, B, and C from top to bottom. Stockpile sub-samples from the Jack Sillmon Heirs property were labeled (SP-1A, SP-1B, and SP-1C. Stockpile sub-samples from the Polly Edwards property were labeled SP-2A, SP-2B, and SP-2C. Stockpile sub-samples from the Helen Carroll property were labeled SP-3A, SP-3B, and SP-3C.

Stockpile sub-samples (SP-1 [A,B,C] through SP-8 [A,B,C]) were then packed into laboratory-provided sample containers, placed on ice in a cooler immediately after collection, and transported by ARCADIS Geraghty & Miller personnel directly to C&ET. A chain of custody record was provided with each cooler containing samples to maintain a record of personnel that had contact with the samples.

The nine stockpile soil sub-samples (SP-1 [A,B,C] through SP-3 [A,B,C]) were composited at C&ET into three composite samples (SP-1, SP-2, and SP-3) and analyzed for high fraction hydrocarbons and low fraction hydrocarbons using USEPA Methods 3550 and 5030, respectively. The results of the soil analyses are discussed in Section 3.2.

Underground Storage Tank Closure Assessment Report

FIELD ACTIVITIES

# 2.5 Excavation Backfilling

At the request of the NCDOT, the excavation pits were not back-filled after the closure samples were collected. The excavation pits were secured with plastic fencing.

Underground Storage Tank Closure Assessment Report

ANALYTICAL RESULTS

### 3. ANALYTICAL RESULTS

This section provides a discussion of the analytical results for the six closure soil samples (HG-1, HG-2, WA-1, WA-2, GC-1, and GC-2) collected from the UST pit bottoms and the three composite soil samples (SP-1, SP-2, and SP-3) collected from the soil stockpiles. A summary of the soil sample identification numbers, collection dates, depths, and analytical results is presented in Table 3-1.

### 3.1 UST Closure Sample Analytical Results

Results for the six closure soil samples (HG-1, HG-2, WA-1, WA-2, GC-1, and GC-2) collected from the UST pit bottoms and analyzed by U.S. EPA Method 3550 and 5030, are summarized in Table 3-1. Analytical laboratory results for the closure samples from all three sites indicate that low and high fraction petroleum hydrocarbons were not detected at concentrations above reportable limits of 0.10 milligrams per kilogram (mg/kg) and 10 mg/kg, respectively. The laboratory analytical reports and chain of custody record for the closure samples are presented in Appendix D.

### 3.2 Stockpile Sample Analytical Results

The nine stockpile sub-samples submitted to C&ET (SP-1 [A,B,C], SP-2 [A,B,C], and SP-3 [A,B,C]) were composited under laboratory controlled climate conditions into three composite samples (SP-1, SP-2, and SP-3) for analyses of low and high fraction hydrocarbons by U.S. EPA Methods 5030 and 3550, respectively. Analytical results for the three composite samples (SP-1, SP-2, and SP-3) are summarized in Table 3-1. Analytical laboratory results for composite stockpile soil samples SP-2 and SP-3 (Polly Edwards and Helen Carroll properties, respectively) indicate that low and high fraction petroleum hydrocarbons were not detected at concentrations above reportable limits of 0.10 mg/kg and 10 mg/kg, respectively. Analytical results for composite stockpile sample SP-1, (Jack Sillmon Heirs property) indicate that low fraction hydrocarbons were not detected at concentrations exceeding the reportable limit of 0.10 mg/kg. However, high fraction hydrocarbons were detected in stockpile sample SP-1 at a concentration of 68.5 mg/kg, which exceeds the reportable limit of 10 mg/kg.

Underground Storage Tank Closure Assessment Report

CONCLUSIONS

### 4. CONCLUSIONS

The following summary presents the key findings and conclusions with respect to the UST Closure activities at the properties formerly owned by Mrs. Polly Edwards (parcel #23). Mrs. Helen Carroll (parcel #961) and the Mr. Jack Sillmon Heirs (parcel #45), Greensboro, North Carolina.

- One 3785 liter (L) UST was removed from the property formerly owned by Mrs. Polly Edwards (parcel #23) on January 5, 1999. The UST formerly contained gasoline. The tank appeared to be in good condition with no visible signs of damage of deterioration. The tank was transported off-site to Safeway Tank Disposal in Colfax, North Carolina.
- One 2082 L UST was removed from the property formerly owned by Mrs. Helen
  Carroll (parcel #961) on January 5, 1999. The UST formerly contained #2 fuel oil.
  The fuel oil had been used as a heating source for the home at the property. The
  tank appeared to be in good condition with no visible signs of damage or
  deterioration. The tank was transported off-site to Safeway Tank Disposal in
  Colfax, North Carolina.
- One 2082 L UST was removed from the property formerly owned Mr. Jack Sillmon Heirs (parcel #45), on January 5, 1999. The UST formerly contained #2 fuel oil. The fuel oil had been used as a heating source for the home at the property. The tank appeared to be in good condition with no visible signs of damage of deterioration. In addition, three ASTs were encountered at this location. All four tanks were transported off-site to Safeway Tank Disposal in Colfax, North Carolina.
- Two closure samples were collected from UST excavation pit bottoms at the former Mrs. Polly Edwards, Mrs. Helen Carroll, and Mr. Jack Sillmon Heirs properties after the tanks were removed (HG-1, HG-2, GC-1, GC-2, WA-1, and WA-2, respectively). Analytical laboratory results for the closure samples from all three sites indicate that low and high fraction petroleum hydrocarbons were not detected at concentrations above reportable limits of 0.10 mg/kg and 10 mg/kg, respectively. These results indicate that clean closures were achieved for each of the three USTs. Therefore, no further action should be required at these locations.

Underground Storage Tank Closure Assessment Report

CONCLUSIONS

- Upon completion of the soil sampling activities the excavation pits at all three
  locations were secured with barricade fencing and left open. The pits will be
  backfilled during road construction which is scheduled to begin in January 1999.
- One composite soil sample was collected from each the soil stockpiles at the Mr. Jack Sillmon Heirs property, Mrs. Polly Edwards property, and Mrs. Helen Carroll property, (SP-1, SP-2 and SP-3, respectively). Analytical results indicate that high fraction hydrocarbons were detected in stockpile sample SP-1 at a concentration of 68.5 mg/kg, which exceeds the reportable limit of 10 mg/kg. Low fraction hydrocarbons were not detected in sample SP-1 at concentrations above reportable limit of 0.10 mg/kg. Analytical results for the stockpile samples SP-2 and SP-3 indicate that that low and high fraction petroleum hydrocarbons were not detected at concentrations above reportable limits of 0.10 mg/kg and 10 mg/kg, respectively.
- The excavated and stockpiled soil at the former Jack Sillmon Heirs property is scheduled to be transported off-site by Soil Solutions, Inc. and will be treated at their facility.

Underground Storage Tank Closure Assessment Report

REFERENCES

# 5. REFERENCES

North Carolina Department of Environment and Natural Resources (NCDENR), 1998a. Groundwater Section Guidelines For the Investigation and Remediation of Soils and Groundwater - Volume II, January 2.

North Carolina Department of Environment and Natural Resources (NCDENR), 1998b. Letter from Burrie Boshoff, Underground Storage Tank Section, to Environmental Service Companies and Consultants, August 24.

Underground Storage Tank Closure Assessment Report

TABLES

Table 2-1. Summary of Underground Storage Tanks (USTs) and Aboveground Storage Tanks (ASTs) removed on January 5, 1999, Guilford College Road Right of Way, State Project No. 8.U492101(U-2524AA), Greensboro, North Carolina.

Former Tank Owner / Location	Type	Disposal Number	Volume (Liters)	Dimensions (Meters)	Contents	Composition
Mrs. Helen Carroll (parcel #961)	UST	1882	2082	1.14 x 1.93	No. 2 Fuel Oil	Steel
Mrs. Polly Edwards (parcel #23)	UST	1884	3785	1.22 x 3.05	Gasoline	Steel
Mr. Jack Sillmon Heirs (parcel #45)			2083	··1.14 x 1.93 ·- ·		Steel
Mr. Jack Sillmon Heirs (parcel #45)	AST	1883	946	0.9 x 1.2	No. 2 Fuel Oil	Steel
Mr. Jack Sillmon Heirs (parcel #45)	AST	9881	1022	1.14 x 1.93	No. 2 Fuel Oil	Steel
Mr. Jack Sillmon Heirs (parcel #45)	AST	1887	2082	0.9 x 1.2	No. 2 Fuel Oil	Steel


Table 3-1. Summary of Soil Analytical Results for UST Closure Samples and Stockpile Samples Collected on January 5, 1999, UST Removals, Guilford College Road, [U-22524AA], Greensboro, North Carolina.

					Closure Samples	Samples			Stock	Stockpile Samples	ples
		Sample ID:	HG-1	HG-2	HG-2 WA-1 WA-2 GC-1	WA-2	1-25 1-25	GC-2	SP-1	SP-2	SP-3
Constituents	Reportable Concentrations	Depth (m bls): Date Sampled:	1,5/99	1.83	1/5/99	75.1 25.1 25.1 1/5/99 1/5/99 1/5/99	1.52	1/5/99	66/5/1	66/5/1 66/5/1	66/\$/1
High Fraction Hydrocarbon (USEPA Method 3550) mg/kg dw	01		01>	01>	<10	<10	<10	<10	68.5	<10	o1>
Low Fraction Hydrocarbon (USEPA Method 5030) mg/kg dw	. 10		01.0>	<0.10	<0.10 <0.10 <0.10 <0.10	<0.10	<0.10	<0.10	<0.10	<0.10	>0.10
% Solids (USEPA Method 2540G) %	NS		82.5	83.1	83.3	83.1	72.1	72.6	77.8	77.6	71.4

Reportable Con	Reportable Concentrations Maximum Soil Contaminant Concentration (NCDENR, 1998b).	Indicates that the total petroleum hydrocarbon has been exceeded (NCDENR, 1998b).	dw Milligrams per kilogram on a dry weight basis.	Meters below the land surface.	Constituent has no standard.	Constituent not analyzed.	mo/kp dw Milligrams per kilogram on a dry weight basis.
----------------	---	---	---	--------------------------------	------------------------------	---------------------------	---

Underground Storage Tank Closure Assessment Report

FIGURES





2301Rexwood Drive Suite 200 RALEICH, NC 27622 Tel: 919/782-5511 Fox: 919/782-5905


DRAWING: FIG 1- ILDGN PRJT NO: NC00054 1.000 I DWG DATE: DRAFTER:


# SITE LOCATION

UST REMOVALS GUILFORD COLLEGE ROAD STATE PROJECT NO. 8.4492 106 [U-2524AA] GREENSBORO, NORTH CAROLINA









Underground Storage Tank Closure Assessment Report

# APPENDIX A

NON-HAZARDOUS WASTE MATERIAL MANIFESTS



# NON-HAZARDOUS WASTE MANIFEST

1701 Vargrave St., Winston-Salem, NC 27107 • 336-727-4644 • Fax 336-727-8840

EPA ID No Contact: ware proper ondition to b	ly described, classified, pace transported in commerce nental Protection Agency a described below is non-haz the carrier named below for	ckaged, e under and the ardous,	
EPA ID No Contact: w are proper ondition to be the Environment the waste	ly described, classified, pace transported in commerce nental Protection Agency a described below is non-haz the carrier named below for	ckaged, e under and the ardous,	
Contact: ware proper ondition to b the Environment the waste	ly described, classified, pace transported in commerce nental Protection Agency a described below is non-haz the carrier named below for	ckaged, e under and the ardous,	
ware proper ondition to b the Environm nat the waste livered to the	ly described, classified, pace e transported in commerce nental Protection Agency a described below is non–haz he carrier named below fo	ckaged, e under and the ardous.	
the Environment the waste	nental Protection Agency a described below is non-haz he carrier named below to	and the ardous.	,
Rohan.			
Commence	Circle Units		rtainer_
Quantity		No.	Туре
200			
293	Cu. Yards/Drums/Tons		
Containe	a registered (licensed) veh	iicle to the ed.	e
I MCHILY HALL	100 Fara	1-5-7	9
	Delivering Driver's Signatu	ıre	Date
Phone N	io: 336-727-4644		
Contact	:	<u></u>	
		<del></del>	
7.	,		
		y and was ialified by	; r
e /-	- 1/10	<del>(/./-</del>	
	Phone N EPA ID N Contains ansierred in ifacility nan Phone N Permit i Contact	Cu. Yards/Drums/Tons  Gallons/Drums  Gallons/Drums/Tons  Gallons/Drums/Tons  Cu. Yards/Drums/Tons  Unit Numbers:  Phone No: 336 70 2-16  EPA ID No:  Container: Lece Truck  ansierred in a registered (licensed) vehal facility named below and was accepted facility named facil	Cu. Yards/Drums/Tons  Cu. Yards/Drums/Tons  Gallons/Drums  Gallons/Drums/Tons  Unit Numbers:  Phone No: 336 70 1- 2000  EPA ID No:  Container: Vect Trice  ansierred in a registered (licensed) vehicle to the facility named below and was accepted.  The Contact:  Phone No: 336-727-4644  Permit No: 34-11TP  Contact:  Vered the specified material to this facility and was above manner. We are authorized and qualified by to handle this material.



# CERTIFICATE OF DISPOSAL

Soil Solutions, Inc. does hereby certify that 593 gallons of non-hazardous contaminated water was transported for disposal on 1/05/99 from:

Generator:

NCDOT

Originating at:

Wendover Avenue Greensboro, NC

SSI Waste ID#:

SF019903

This non-hazardous material has been disposed of by Soil Solutions, Inc. in a manner approved by the North Carolina Department of Environment and Natural Resources.

Signature

Thomas W. Hammett Sr. Vice President Soil Solutions, Inc.

Underground Storage Tank Closure Assessment Report

APPENDIX B

CERTIFICATES OF DISPOSAL FOR USTS AND ASTS

1

Page of RECEIVING REPORT Received by: SAFEWAY TANK DISPOSAL, INC. District by CUMGN TENK DISPOSAL Weight Number 000 550 450 250 884 2-20 450 188 550

Saleway Tank Disposal. Inc. accepts the literal defined sank (s) and contents on this report. The tank (s) and contents must be a petroleum product. If it may time the tanks are found to contain any product other than a petroleum product of the than a petroleum product of the disposal or negotiate a price of the product of the cost resulting from containing the product of the cost resulting from containing the product of petroleum tanks and contents in Saleway Tank. Olsposal, Inc. 1988.

MAN TANK DISPOSAL INC.

Underground Storage Tank Closure Assessment Report

APPENDIX C

UST CLOSURE FORMS (UST-2) AND UST CLOSURE REPORTS (GW/UST-12)

CMARIC							Ob-	- Culton of ICT
FOR TANKS IN NC	Return Completed For The appropriate DEM R	m To: egional Office according SE SIDE OF OWNER'S C	to the county (COPY (PINK) i	of the fa	cility's lo	ocation.	State I.D. N	Use Only Sumber Received
<u> </u>		Complete and return within			letion of	site inves	tigation	
	I. Ownership of Tank		(30) days 10110w	ning contp	ile do il o			of Tank(s)
Owner Name		dwards		Facilit	y Name			wiirds Preserby
Corporation, indiv	vidual, Public Agency, or Other Entity) SS: 5916 Hicke	on Gray Rad		(ог Соп	ipany)	f available		, , , , , , , , , , , , , , , , , , ,
	=nulford	1						y Grove Roid
	s bois State: NC	7: Codo: 274	10			i(for 1		Greenster zip Code: 27410
	umber: ()		<u>~~</u>   -				)	
<u> </u>	(Area Code)				none ivi		ea Code)	
		<u></u>	III. Contact (		1 -			/ X
			•			~		Tel. No. (919) 250-4088
			; ~		•		_	Tel. No. (336) 725-5844
Primary Cons	ultant: ARCADIS Extrast	Ay & Miller Address:	2301 Ruxu	1 6 P 3 2	)r Su.	e 200	<u> Ribigh</u>	NC Tel. No. : 119 782-5511
Lab: Chern							CANY !	JC Tel. No.: (919)735-7353
	IV. U.S.T. Information	π :	V.Ex	<u>:\/}:(()</u> 			Odoror	VI. Additional Information Required
	e in Tank Tons Dimensions	Last	Excavation	Prod	uct		Contamination	See reverse side of pillik copy
		Contents	Yes No	Yes	No No	res	X	(owner's copy) for additional information required by N.C DEM
1 10	00 44 × 164	Gasoline		-	X		;	in the written report and sketch.
								NOTE: The site assessment portion
			i					of the tank closure must be con- ducted under the supervision of a
						ļ		Professional Engineer or Licensed Geologist. After Jan.1, 1994, all
							1	closure site assessment reports must be signed and sealed
				<del> </del>	<u> </u>		!	by a P.E. or L.G.
			A (Charlesha					•
Fisher Control		VII. Check Lis	ar (ensertins	⊞#IIMII(	2140111	bierea)	·	
PERMANI	ENT CLOSURE (For Removi	ng or Abandoning-in-place	5) .					•
	tact local fire marshal. fy DEM Regional Office before	abandonment.	i	A	BANDO	NMENT II	PLACE	
Drai	n & flush piping into tank. nove all product and residuals		:		_		material of	verflows tank opening. s.
Exca	avate down to tank. an and inspect tank.		ı		Dis	sconnect a	ind cap or	remove vent line. d - specify:
Rem	nove drop tube, fill pipe, gauge		connections,					
Cap	mersible pumps and other tan or plug all lines except the ve	nt and fill lines.	:	E	EMOVA	. <u>L</u> eate vent l		
Cut	ge tank of all product & flamm one or more large holes in the				Κ La	bel tank.		
Date	kfill the area. e Tank(s) Permanently close		<u> </u>	-				oved manner. Sateway Track Disposal, I
Date	e of Change-in-Service:					1501	HW74	21, Colfax, NC
		VIII. C	ertification (	Read a	rd Sigr	)		
I certify un	der penalty of law that I	have personally exam	ined and am	familia	r with t	he inforr	nation st	ubmitted in this and all attached
	s, and that based on my information is true, accu		duals immed	ately re	spons	ible for c	ptaining	the information, I believe that the
	nd official title of owner or own			Sign	ature		<u> </u>	Date Signed

Signature

2/1/99

Print name and official title of owner or owner's authorized representative

Variable from the Francisco to

# GW/UST-12 UNDERGROUND STORAGE TANK CLOSURE REPORT

# Underground Storage Tank Closure Assessment Report for 5916 Hickory Grove Road, Greensboro, North Carolina, 27410

### I. General Information

# A. Ownership of UST(s)

1. **Name of UST Owner:**Formerly, Mrs. Polly Edwards

 Owner Address and Telephone Number: 5916 Hickory Grove Road, Greensboro, North Carolina, 27410

# B. Operator of UST(s)

1. Name of UST operator:

2. Operator address and telephone number: N/A

# C. Facility Information

- 1. Facility name: 5916 Hickory Grove Road, Greensboro, North Carolina, 27410
- 2. Facility ID #: N/A
- 3. Facility address, telephone number, and county: 5916 Hickory Grove Road, Greensboro, North Carolina, 27410

# D. Contacts

Name, address, telephone number, and job title of primary contact person:
 Eugene Tarascio, Project Environmental Geologist
 North Carolina Department of Transportation
 P.O. Box 25201, Raleigh, NC 27611-5201
 (919) 250-4088

2. Name, address, and telephone number of closure contractor:

Soil Solutions, Inc. 1703 Vargrave Street, Winston Salem, NC 27107 (336) 725-5844 3. Name, address, and telephone number of primary consultant:

ARCADIS Geraghty & Miller, Inc. 2301 Rexwoods Drive, Suite 200 Raleigh, North Carolina 27607 (919) 782-5511

4. Name, address, telephone number, and State certification number of laboratory:

Chemical and Environmental Technologies, Inc.

102-A woodwinds Industrial Court

Cary, NC 27511 (919) 735-7353

State Certification Number: DWQ - 96; Public Water Supply - 37724

5. Name, address, and telephone number of Soil Disposal Contractor:

Soil Solutions, Inc. 1703 Vargrave Street, Winston-Salem, NC 27107 (336) 725-5844

# E. UST Information

Tank No.	Installation dates	Size in Gallons	Tank Dimensions	Last Contents	Previous Contents (if any)
1	Unknown	1000	4 ft. x 10 ft.	Gasoline	Unknown

# F. Site Characteristics

1. Describe any past releases at this site.

It is unknown if any previous releases have occurred at the subject site.

2. Is the facility active or inactive at this time? If the facility is inactive, note the last time the USTs were in operation.

The tanks were inactive at the time of removal. The last time the UST was operational is unknown.

3. Describe surrounding property use (for example, residential, commercial, farming, etc.).

### Residential/Farmland

4. Describe site geology/ hydrogeology.

Soil underlying this site consists predominantly of variably silty clay ranging in color from dark reddish brown to grayish brown, with minor amounts of silty sand. Bedrock was not encountered during excavation activities, but is reportedly comprised of metamorphosed granitic rock.

5. Describe results of receptor survey (water wells, basements, etc., within 1500 feet of the facility).

N/A

# II. Closure Procedures

A. Describe preparations for closure including the steps taken to notify authorities, permits obtained, and the steps taken to clean and purge the tanks.

The tank is non-regulated so permits were not required to be obtained. On January 5, 1999, a vacuum truck and dry ice were used to purge the tank of liquid product and vapors. Then, Soil Solutions, Inc. of Winston-Salem, North Carolina, inspected the UST to determine if the tank was safe for excavation and removal. Vapor concentrations within the UST were monitored by SSI by placing a Combustible Gas Indicator (CGI) probe in the fill opening. Readings of 10 percent or less of the Lower Explosive Limit (LEL) were obtained before the tank was considered to be safe for removal. The Certificate of Disposal for the tank is provided in Appendix C.

- B. Note the amount of residual material pumped from the tank(s). Less than 50 gallons.
- C. Describe the storage, sampling, and disposal of the residual material.

  Fuel and fuel/water mixtures were transported off-site and disposed of by Soil Solutions at HOH

  Corporation, 1701 Vargrave Street, Winston Salem, North Carolina. Copies of the non-hazardous waste manifests are presented in the Appendix D.
- D. Excavation
  - 1. Describe excavation procedures noting the condition of the soil encountered and the dimensions of the excavation in relation to the tanks, piping, and/or pumps.

On January 5, 1999, Soil Solutions began excavating soils from above and around the UST. ARCADIS Geraghty & Miller personnel field screened the soil for volatile compounds using a MiniRAE organic vapor meter, which operates by photoionization detection (PID). Samples were screened by placing a portion of the sample into a resealable bag. The bag was then closed for about 5 minutes to allow the bag's headspace

to equilibrate with the volatile organic compounds (VOCs) in the soil. The PID probe was then inserted into the bag's headspace and the resultant PID reading was recorded.

The dimensions of the excavation pit necessary to remove the UST was approximately 6 feet in width by 19 feet in length.

# 2. Note the depth of tank burial(s) (from land surface to top of tank).

The top of the UST was located 3 feet below land surface. The bottom of the tank was located at approximately 6 feet below lands surface. The tanks were resting on and surrounded by soil.

### 3. Note volume of soil excavated.

Only soil necessary to remove the tank was excavated and stockpiled on polyethylene sheeting near the excavation pit and within the NCDOT right-of-way. The stockpiled soil (approximately 15 cubic meters) was covered with a polyethylene liner and contained on all sides with bails of straw. One hand-augered soil boring was advanced within the stockpile.

# 4. Describe soil type(s) encountered.

The soil encountered at the site was generally silty clay ranging in color from dark reddish brown to grayish brown, with minor amounts of silty sand.

# 5. Describe type and source of backfill used.

At the request of the NCDOT the excavation pit was secured with barricade fencing and not backfilled.

# 6. Describe condition of UST system(s) (i.e., pitting, holes, etc.).

The physical condition of the tank was good. No pitting or holes were observed.

# 7. Note if the excavation reached the groundwater table or bedrock surface.

Neither groundwater nor bedrock were encountered in the excavation pit.

### E. Contaminated Soil

# 1. Describe how it was determined to what extent to excavate the soil.

ARCADIS Geraghty & Miller guided the excavation activities by visually inspecting and screening soil samples with an OVM. Samples were screened by placing a portion of the sample into a resealable bag. The bag was then closed for about 5 minutes to allow the bag's headspace to equilibrate with the VOCs in the soil. The OVM probe was then inserted into the bag's headspace and the resultant OVM reading was recorded. Visual observations and screening by OVM indicated that no impacted soil was present in the bottom or side walls of the tank pits, after the tank was removed.

# 2. Describe method of temporary storage, sampling, and treatment/disposal of soil.

Only soil necessary to remove the tank was excavated and stockpiled on polyethylene sheeting near the excavation pit and within the NCDOT right-of-way. The stockpiled soil

(approximately 15 cubic meters) was covered with a polyethylene liner and contained on all sides with bails of straw. One hand-augered soil boring was advanced within the stockpile. Three discrete sub-samples (SP-2A, SP-2B, SP-2C) were collected from three depths at each of the boring locations. Stockpile sub-samples were then packed into laboratory-provided sample containers, placed on ice in a cooler immediately after collection, and transported by ARCADIS Geraghty & Miller personnel directly to C&ET. A chain of custody record was provided with each cooler containing samples to maintain a record of personnel that had contact with the samples. A copy of the chain of custody is provided in Appendix E.

The stockpile soil sub-samples were composited at C&ET into three composite samples and analyzed for high fraction hydrocarbons and low fraction hydrocarbons using USEPA Methods 3550 and 5030, respectively. Analytical results indicated that high and low fraction hydrocarbons were not detected in concentrations that exceed reportable limits of 10 mg/kg and 0.10 mg/kg, respectively. A copy of the laboratory analytical results is provided in Appendix F. The excavated soil remains at the site and will likely be used backfill the excavation pit when road construction begins.

# III. Site Investigation

A. Provide information on field screening and physical observations, as well as methods used to calibrate field screening instrument(s).

ARCADIS Geraghty & Miller guided the excavation activities by visually inspecting and screening periodic soil samples with an OVM. OVM screening procedures were discussed in previous sections. The OVM was calibrated on at least a daily basis using a zero gas and a 100 part per million by volume (ppmv) isobutylene calibration gas.

- B. Describe soil sampling points and sampling procedures used.
  - 1. Samples Associated with Underground Storage Tanks.

    A total of two grab samples were collected for laboratory analysis from the UST pit bottom directly below the UST after it was removed. Samples, labeled HG-1 and HG-2, were collected from approximately 6 to 6.5 feet below land surface. samples were then packed into laboratory-provided sample containers, placed on ice in a cooler immediately after collection, and transported by ARCADIS Geraghty & Miller personnel directly to C&ET. A chain of custody record was provided with each cooler containing samples to maintain a record of personnel that had contact with the samples. A copy of the chain of custody is provided in Appendix E.

Soil samples were analyzed for high fraction hydrocarbons and low fraction hydrocarbons using USEPA Methods 3550 and 5030, respectively. Analytical results indicated that high and low fraction hydrocarbons were not detected in concentrations that exceed reportable limits of 10 mg/kg and 0.10 mg/kg, respectively. A copy of the laboratory analytical results is provided in Appendix F.

2. Samples Associated with Pipeline and Transfer Lines.

No samples were taken because no pipelines or transfer lines were present.

#### C. Describe groundwater or surface water sampling procedures

Groundwater or surface water samples were not collected during this investigation

#### D. Describe quality control measures

Stainless steel spoons were used to collect the soil samples directly from the backhoe bucket. Fresh latex gloves were worn while the soil was transferred from the sampling devices to the laboratory-supplied containers. Sampling equipment was decontaminated between each location with a clean water rinse, soapy water wash, followed by a clean water rinse.

The sample containers were labeled, placed in ice-filled coolers, and then remained in the custody of an ARCADIS Geraghty & Miller representative until delivery to C&ET in Cary, North Carolina.

Quality control samples were not collected during the UST closure activities.

#### E. Describe investigation results, including:

#### 1. Tank Removal Analytical Results

Constituents	HG-1	HG-2
	!	<del>-</del>
High Fraction Hydrocarbons USEPA Method 3550 (mg/kg dw)	<10.0	<10.0
Low Fraction Hydrocarbons USEPA Method 5030(mg/kg dw)	<0.10	<0.10

- 2. Pipeline Analytical Results
- 3. Transfer Line Analytical Results
  N/A

#### IV. Conclusions and Recommendations

Field observations and analytical results indicate that a clean closure of this UST has been achieved. No further action should be required at this site.

### V. Signature and Seal of Professional Engineer or Licensed Geologist

William H. Doucette, Jr. Ph.D., L.G./ Associate/Project Manager



VI. Enclosures

		· ·					
V/US	T-2 Site	Investigation Re	ort For Perm	anent t	Closure	e or Ch	ange-in-Service of U.S.T.
OR NKS IN	Return Completed Fo The appropriate DEM I		to the county of th	e facility's	location.	State I.D. N	Use Only Number Received
			INSTRUCTIONS	100			
<del>,</del>		Complete and return within	(30) days following o	ompletion o			
	I. Ownership of Tan				11.	Location	of Tank(s)
r Name	Mrs. Helen Ca	110.7			e: 1-1el	en Ca.	roll Property
Addre:	ndual, Public Agency, or Other Entity)	Ford Glisse Road		r Company) acility ID #	(if available	e):	
v:	Suil G 2	,	) s	treet Addre	ess 230	D- 910 5	Emil Field Cellege Road
مَ وَالْمُوالِدُ	Shore State: No	Zip Code: 2741		r State Board	Ο.		Greenshire Zip Code: 27412
ion <u>e N</u>	umber: ()	N/A		elephone N	lumber: (		4\0
	(Area Code)		III. Contact Pers	čite:	A) .	(rea Code)	
Ġ.,	ne Tapascio (NCC	· · · · · · · · · · · · · · · · · · ·			11-		10:00 3-
			Project Env			J	
	ector: Soil Schutrons						
	ultant: ARCADIS Econo						
مولدزاز	1 \$ Env. ronmantal	Technologies Address:	102-A Wazdulin	ds Indu	Striel Co	t, Cary	NC Tel. No. : (19) 735-735
•	IV. U.S.T. Informati	on	V. Excava	tion Con	dition		VI. Additional Information Required
Size Gal	e in Tank lons Dimensions	Last Contents	Water in Excavation :	Free Product		e Odor or Contamination No	See reverse side of pink copy (owner's copy) for additional
<b>5</b> 5	3.75f+ X E F+	#2 fuel Oil	×	$\times$		X	information required by N.C DEN in the written report and sketch.
							NOTE: The <u>site assessment</u> portio of the tank closure must be con- ducted under the supervision of a Professional Engineer or Licensed Geologist. After Jan.1, 1994, all closure site assessment reports must be signed and sealed by a P.E. or L.G.
	·		it (Check the activ				:
Cont Notif Drain Rem Exca Clea Rem	act local fire marshal.  y DEM Regional Office before a flush piping into tank, ove all product and residuals vate down to tank, and inspect tank, ove drop tube, fill pipe, gaug- nersible pumps and other tan or piug all lines except the ve	ing or Abandoning-in-place e abandonment. from tank. e pipe, vapor recovery tank of k fixtures.	<u>}1</u>	ABANDO Fi Pl	ONMENT II II tank until lug or cap a isconnect a olid inert m	material ov all openings and cap or r	verflows tank opening. : emove vent line. I - specify:
Purg Cut o Back Date	or plug all lines except the ve e tank of all product & flamm one or more large holes in the fill the area. Tank(s) Permanently close of Change-in-Service:	able vapors. e tanks. ed:		CI	reate vent l abel tank.		oved manner. Tank Disposal: Sateway Tank Disposal: 421, Colfac NC
			<u> </u>				

mitted information is true, accurate, and complete.

. name and stitual title of owner or owner's authorized representative Date Signed Signature 2/1/99

#### **GW/UST-12 UNDERGROUND STORAGE TANK CLOSURE REPORT**

# Underground Storage Tank Closure Assessment Report for 830-910 Guilford College Road, Greensboro, North Carolina, 27410

#### I. General Information

#### A. Ownership of UST(s)

1. Name of UST Owner:

Formerly, Mrs. Helen Carroll

Owner Address and Telephone Number:
 830-910 Guilford College Road, Greensboro, North Carolina, 27410

#### B. Operator of UST(s)

1. Name of UST operator:

N/A

2. Operator address and telephone number: N/A

#### C. Facility Information

- 1. Facility name: 830-910 Guilford College Road, Greensboro, North Carolina, 27410
- 2. Facility ID #: N/A
- 3. Facility address, telephone number, and county:
  830-910 Guilford College Road, Greensboro, North Carolina, 27410

#### D. Contacts

1. Name, address, telephone number, and job title of primary contact person:

Eugene Tarascio, Project Environmental Geologist North Carolina Department of Transportation P.O. Box 25201, Raleigh, NC 27611-5201 (919) 250-4088

2. Name, address, and telephone number of closure contractor:

Soil Solutions, Inc. 1703 Vargrave Street, Winston Salem, NC 27107 (336) 725-5844 3. Name, address, and telephone number of primary consultant:

ARCADIS Geraghty & Miller, Inc. 2301 Rexwoods Drive, Suite 200 Raleigh, North Carolina 27607 (919) 782-5511

4. Name, address, telephone number, and State certification number of laboratory:

Chemical and Environmental Technologies, Inc.

102-A woodwinds Industrial Court

Cary, NC 27511 (919) 735-7353

State Certification Number: DWQ - 96; Public Water Supply - 37724

5. Name, address, and telephone number of Soil Disposal Contractor:

Soil Solutions, Inc. 1703 Vargrave Street, Winston-Salem, NC 27107 (336) 725-5844

E. UST Information

Tank No.	Installation dates	Size in Gallons	Tank Dimensions	Last Contents	Previous Contents (if any)
1	Unknown	550	3.75 ft. x 6 ft.	#2 Fuel Oil	Unknown

#### F. Site Characteristics

1. Describe any past releases at this site.

It is unknown if any previous releases have occurred at the subject site.

2. Is the facility active or inactive at this time? If the facility is inactive, note the last time the USTs were in operation.

The tanks were inactive at the time of removal. The last time the UST was operational is unknown.

3. Describe surrounding property use (for example, residential, commercial, farming, etc.).

#### Residential/Farmland

4. Describe site geology/ hydrogeology.

Soil underlying this site consists predominantly of variably silty clay ranging in color from dark reddish brown to grayish brown, with minor amounts of silty sand. Bedrock was not encountered during excavation activities, but is reportedly comprised of metamorphosed granitic rock.

5. Describe results of receptor survey (water wells, basements, etc., within 1500 feet of the facility).

N/A

#### II. Closure Procedures

A. Describe preparations for closure including the steps taken to notify authorities, permits obtained, and the steps taken to clean and purge the tanks.

The tank is non-regulated so permits were not required to be obtained. On January 5, 1999, a vacuum truck and dry ice were used to purge the tank of liquid product and vapors. Then, Soil Solutions, Inc. of Winston-Salem, North Carolina, inspected the UST to determined if the tank was safe for excavation and removal. Vapor concentrations within the UST were monitored by SSI by placing a Combustible Gas Indicator (CGI) probe in the fill opening. Readings of 10 percent or less of the Lower Explosive Limit (LEL) were obtained before the tank was considered to be safe for removal. The Certificate of Disposal for the tank is provided in Appendix C.

- B. Note the amount of residual material pumped from the tank(s).

  Approximately 1100 liters.
- C. Describe the storage, sampling, and disposal of the residual material.

  Fuel and fuel/water mixtures were transported off-site and disposed of by Soil Solutions at HOH Corporation, 1701 Vargrave Street, Winston Salem, North Carolina. Copies of the non-hazardous waste manifests are presented in the Appendix D.

#### D. Excavation

1. Describe excavation procedures noting the condition of the soil encountered and the dimensions of the excavation in relation to the tanks, piping, and/or pumps.

On January 5, 1999, Soil Solutions began excavating soils from above and around the UST. ARCADIS Geraghty & Miller personnel field screened the soil for volatile compounds using a MiniRAE organic vapor meter, which operates by photoionization detection (PID). Samples were screened by placing a portion of the sample into a resealable bag. The bag was then closed for about 5 minutes to allow the bag's headspace

to equilibrate with the volatile organic compounds (VOCs) in the soil. The PID probe was then inserted into the bag's headspace and the resultant PID reading was recorded.

The dimensions of the excavation pit necessary to remove the UST was approximately 6 feet in width by 19 feet in length.

#### 2. Note the depth of tank burial(s) (from land surface to top of tank).

The top of the UST was located 3 feet below land surface. The bottom of the tank was located at approximately 5 feet below lands surface. The tanks were resting on and surrounded by soil.

#### 3. Note volume of soil excavated.

Only soil necessary to remove the tank was excavated and stockpiled on polyethylene sheeting near the excavation pit and within the NCDOT right-of-way. The stockpiled soil (approximately 9 cubic meters) was covered with a polyethylene liner and contained on all sides with bails of straw.

#### 4. Describe soil type(s) encountered.

The soil encountered at the site was generally silty clay ranging in color from dark reddish brown to grayish brown, with minor amounts of silty sand.

#### 5. Describe type and source of backfill used.

At the request of the NCDOT the excavation pit was secured with barricade fencing and not backfilled.

#### 6. Describe condition of UST system(s) (i.e., pitting, holes, etc.).

The physical condition of the tank was good. No pitting or holes were observed.

#### 7. Note if the excavation reached the groundwater table or bedrock surface.

Neither groundwater nor bedrock were encountered in the excavation pit.

#### E. Contaminated Soil

#### 1. Describe how it was determined to what extent to excavate the soil.

ARCADIS Geraghty & Miller guided the excavation activities by visually inspecting and screening soil samples with an OVM. Samples were screened by placing a portion of the sample into a resealable bag. The bag was then closed for about 5 minutes to allow the bag's headspace to equilibrate with the VOCs in the soil. The OVM probe was then inserted into the bag's headspace and the resultant OVM reading was recorded. Visual observations and screening by OVM indicated that no impacted soil was present in the bottom or side walls of the tank pits, after the tank was removed.

## 2. Describe method of temporary storage, sampling, and treatment/disposal of soil.

Only soil necessary to remove the tank was excavated and stockpiled on polyethylene sheeting near the excavation pit and within the NCDOT right-of-way. The stockpiled soil (approximately 9 cubic meters) was covered with a polyethylene liner and contained on all

sides with bails of straw. One hand-augered soil boring was advanced within the stockpile. Three discrete sub-samples (SP-3A, SP-3B, SP-3C) were collected from three depths at each of the boring locations. Stockpile sub-samples were then packed into laboratory-provided sample containers, placed on ice in a cooler immediately after collection, and transported by ARCADIS Geraghty & Miller personnel directly to C&ET. A chain of custody record was provided with each cooler containing samples to maintain a record of personnel that had contact with the samples. A copy of the chain of custody is provided in Appendix E.

The stockpile soil sub-samples were composited at C&ET into three composite samples and analyzed for high fraction hydrocarbons and low fraction hydrocarbons using USEPA Methods 3550 and 5030, respectively. Analytical results indicated that high and low fraction hydrocarbons were not detected in concentrations which exceed reportable limits of 10mg/kg and 0.10 mg/kg, respectively. A copy of the laboratory analytical results is provided in Appendix F. The excavated soil remains at the site and will likely be used back fill the excavation pit when road construction begins.

#### III. Site Investigation

A. Provide information on field screening and physical observations, as well as methods used to calibrate field screening instrument(s).

ARCADIS Geraghty & Miller guided the excavation activities by visually inspecting and screening periodic soil samples with an OVM. OVM screening procedures were discussed in previous sections. The OVM was calibrated on at least a daily basis using a zero gas and a 100 part per million by volume (ppmv) isobutylene calibration gas.

- B. Describe soil sampling points and sampling procedures used.
  - 1. Samples Associated with Underground Storage Tanks.

A total of two grab samples were collected for laboratory analysis from the UST pit bottom directly below the UST after it was removed. Samples, labeled GC-1 and GC-2, were collected from approximately 5 to 5.5 feet below land surface. samples were then packed into laboratory-provided sample containers, placed on ice in a cooler immediately after collection, and transported by ARCADIS Geraghty & Miller personnel directly to C&ET. A chain of custody record was provided with each cooler containing samples to maintain a record of personnel that had contact with the samples. A copy of the chain of custody is provided in Appendix E.

Soil samples were analyzed for high fraction hydrocarbons and low fraction hydrocarbons using USEPA Methods 3550 and 5030, respectively. Analytical results indicated that high and low fraction hydrocarbons were not detected in concentrations that exceed reportable limits of 10 mg/kg and 0.10 mg/kg, respectively. A copy of the laboratory analytical results is provided in Appendix F.

2. Samples Associated with Pipeline and Transfer Lines.

No samples were taken because no pipelines or transfer lines were present.

C. Describe groundwater or surface water sampling procedures
Groundwater or surface water samples were not collected during this investigation

#### D. Describe quality control measures

Stainless steel spoons were used to collect the soil samples directly from the backhoe bucket. Fresh latex gloves were worn while the soil was transferred from the sampling devices to the laboratory-supplied containers. Sampling equipment was decontaminated between each location with a clean water rinse, soapy water wash, followed by a clean water rinse.

The sample containers were labeled, placed in ice-filled coolers, and then remained in the custody of an ARCADIS Geraghty & Miller representative until delivery to C&ET in Cary, North Carolina.

Quality control samples were not collected during the UST closure activities.

#### E. Describe investigation results, including:

#### 1. Tank Removal Analytical Results

Constituents	GC-1	GC-2
High Fraction Hydrocarbons USEPA Method 3550 (mg/kg dw)	<10.0	<10.0
Low Fraction Hydrocarbons USEPA Method 5030(mg/kg dw)	<0.10	<0.10

- 2. Pipeline Analytical Results
  N/A
- 3. Transfer Line Analytical Results
  N/A

#### IV. Conclusions and Recommendations

Field observations and analytical results indicate that a clean closure of this UST has been achieved. No further action should be required at this site.

### V. Signature and Seal of Professional Engineer or Licensed Geologist

William H. Doucette, Jr. Ph.D., L.G.

Associate/Project Manager



VI. Enclosures

- ALL	ander o		1						
	/UST-2	Site I	nvestigation Rep	ort For	Perma	nent C	losure	or Cha	inge-in-Service of U.S.T.
FC TAN		turn Completed Forr						State	Use Only
1A1	[ 110	e appropriate DEM Re	egional Office according E SIDE OF OWNER'S (	to the coun	ty of the f	acility's l	ocation.		lumber
N	10-	FICE ADDRESS].	E SIDE OF OWNERS	SOFT (FINE	V) FOR R	EGIONA	<u>.</u>		Received
1 1				INSTRUC	PAONS:	,			
	<u> </u>		Complete and return within			noletion of	site investi	dation.	<del></del> -
	1.	. Ownership of Tank							of Tank(s)
TWDA		ack Silmon 1				Ca. Nama		•	Illmon Heirs Property
Street	on incividual, Pu	Ublic Agency, or Other Entity)	endover Avenue		(or C	ility Name ompany)	f available):		J/A
County	<i>i</i> ' \	^ .	Control   100 control				s 480		st Windower Avenue
Dity:	i eens b		Zip Code: 2741	<u>ə</u>	(or St	(ate Boad)	1.1.fe6		Greensbergzip Code: 27410
<u>Teleph</u>	one Number				Telé	phone Ni	ımber: (	۱	AIG
		(Area Code)		III. Conta				a Code)	
	(-)			•			-		- land a - a
		Termsile (NODE)	-	Ruject E			~		Tel. No. : (119) 250-4088
		Soil Schutrons,		1703 Veria	•	*		,	Tel. No. : <b>33₺)</b> 775 - 5844
4.		ARCADIS Elected	•	2301 Rek					
_ab: (		Environ mental Tec						روره ا	1, NO Tel. No. : (119)735-7353
·	- 1	V. U.S.T. İnformatio		Water in	≛neavalit	iee	Notable	Odoroz	VI. Additional Information Required
Tank	Size in	Tank	Last	Excavatio	n Pr	oduct	Visible Soil Co	ontamination	See reverse side of pink copy
No.	Gallons	Dimensions	Contents	Yes N		No No	Yes	No	(owner's copy) for additional information required by N.C DEM
)	<u> 550</u>	3.75 F1 x 6.00 FT	#2 Fuel Oil		X	×	X		in the written report and sketch.
									NOTE: The site assessment portion
									of the tank closure must be con-
	<u>.</u>				<del></del>				ducted under the supervision of a Professional Engineer or Licensed
									Geologist. After Jan.1, 1994, all
'									closure site assessment reports  must be signed and sealed
							<del>                                     </del>		by a P.E. or L.G.
						<u> </u>		_	
	<u> </u>		VII. Check Lis	ar (Queston	Ne alctivit	ies com	pleter)		
PER	MANENT C	LOSURE (For Removin	<u>g or Abandoning-in-plac</u>	<u>e)</u>			-		
		al fire marshal.				ARANDO	NMENT IN	PLACE	
		A Regional Office before sh piping into tank.	abandonment.						verflows tank opening.
3		I product and residuals f	rom tank.			Plu Plu	g or cap all	lopenings	·
$\overline{\mathbf{x}}$	Excavate of Clean and	lown to tank. inspect tank.		:					emove vent line. I - specify:
	Remove dr	rop tube, fill pipe, gauge	pipe, vapor recovery tank	connections;					
	Cap or plug	le pumps and other tank g all lines except the ver	nt and fill lines.		l	REMOVA			
$\succeq$		of all product & flamma more large holes in the		!			eate vent hi bel tank.		
	Backfill the	area.		!		Di:	spose of tar	nk in appro	oved manner. Section of Truk Disposel, Inc
į		(s) Permanently closed ange-in-Service:	d:	<u> </u>		Fir	nal tank des 4 C∆I L	stination: . ねみてリレ	1. Colfix, NC
				- ,				<u>, -0   10</u>	
				Certification	•				
: certif	y under pe	enalty of law that I h	nave personally exam	ined and a	m familia	ar with t	he inform	iation su staining	bmitted in this and all attached the information, I believe that the
		nation is true, accur		Juais iiiiiitt	Julialely I	Copons	DIC TOT OL	,	pic internation, i politic that the

Signature

Frint name and official title of owner or owner's authorized representative

Date Signed

### **GW/UST-12 UNDERGROUND STORAGE TANK CLOSURE REPORT**

# Underground Storage Tank Closure Assessment Report for 4812 W. Wendover Road, Greensboro, North Carolina, 27410

#### I. General Information

#### A. Ownership of UST(s)

1. Name of UST Owner:

Formerly, Jack Sillmon Heirs

2. Owner Address and Telephone Number:

Formerly, 4812 W. Wendover Road, Greensboro, North Carolina, 27410 (dwelling has recently been demolished)

#### B. Operator of UST(s)

1. Name of UST operator:

N/A

2. Operator address and telephone number:

N/A

#### C. Facility Information

- 1. Facility name: 4812 W. Wendover Road, Greensboro, North Carolina, 27410
- 2. Facility ID #: N/A
- 3. Facility address, telephone number, and county:

Formerly, 4812 W. Wendover Road, Greensboro, North Carolina, 27410 (dwelling has recently been demolished)

#### D. Contacts

1. Name, address, telephone number, and job title of primary contact person:

Eugene Tarascio, Project Environmental Geologist North Carolina Department of Transportation P.O. Box 25201, Raleigh, NC 27611-5201 (919) 250-4088

2. Name, address, and telephone number of closure contractor:

Soil Solutions, Inc. 1703 Vargrave Street, Winston Salem, NC 27107 (336) 725-5844 3. Name, address, and telephone number of primary consultant:
ARCADIS Geraghty & Miller, Inc.
2301 Rexwoods Drive, Suite 200
Raleigh, North Carolina 27607
(919) 782-5511

4. Name, address, telephone number, and State certification number of laboratory:

Chemical and Environmental Technologies, Inc.

102-A woodwinds Industrial Court

Cary, NC 27511 (919) 735-7353

State Certification Number: DWQ - 96; Public Water Supply - 37724

5. Name, address, and telephone number of Soil Disposal Contractor:

Soil Solutions, Inc. 1703 Vargrave Street, Winston-Salem, NC 27107 (336) 725-5844

#### E. UST Information

Tank No.	Installation dates	Size in Gallons	Tank Dimensions	Last Contents	Previous Contents (if any)
1	Unknown	550	3.75 ft. x 6 ft.	#2 Fuel Oil	Unknown

#### F. Site Characteristics

1. Describe any past releases at this site.

It is unknown if any previous releases have occurred at the subject site.

2. Is the facility active or inactive at this time? If the facility is inactive, note the last time the USTs were in operation.

The tanks were inactive at the time of removal. The last time the UST was operational is unknown.

3. Describe surrounding property use (for example, residential, commercial, farming, etc.).

#### Residential/Farmland

4. Describe site geology/ hydrogeology.

Soil underlying this site consists predominantly of variably silty clay ranging in color from dark reddish brown to grayish brown, with minor amounts of silty sand. Bedrock was not encountered during excavation activities, but is reportedly comprised of metamorphosed granitic rock.

5. Describe results of receptor survey (water wells, basements, etc., within 1500 feet of the facility).

N/A

#### II. Closure Procedures

A. Describe preparations for closure including the steps taken to notify authorities, permits obtained, and the steps taken to clean and purge the tanks.

The tank is non-regulated so permits were not required to be obtained. On January 5, 1999, a vacuum truck and dry ice were used to purge the tank of liquid product and vapors. Then, Soil Solutions, Inc. of Winston-Salem, North Carolina, inspected the UST to determine if the tank was safe for excavation and removal. Vapor concentrations within the UST were monitored by SSI by placing a Combustible Gas Indicator (CGI) probe in the fill opening. Readings of 10 percent or less of the Lower Explosive Limit (LEL) were obtained before the tank was considered to be safe for removal. The Certificate of Disposal for the tank is provided in Appendix C.

- B. Note the amount of residual material pumped from the tank(s). Less than 50 gallons.
- C. Describe the storage, sampling, and disposal of the residual material.

  Fuel and fuel/water mixtures were transported off-site and disposed of by Soil Solutions at HOH

  Corporation, 1701 Vargrave Street, Winston Salem, North Carolina. Copies of the non-hazardous waste manifests are presented in the Appendix D.

#### D. Excavation

1. Describe excavation procedures noting the condition of the soil encountered and the dimensions of the excavation in relation to the tanks, piping, and/or pumps.

On January 5, 1999, Soil Solutions began excavating soils from above and around the UST. ARCADIS Geraghty & Miller personnel field screened the soil for volatile compounds using a MiniRAE organic vapor meter, which operates by photoionization detection (PID). Samples were screened by placing a portion of the sample into a resealable bag. The bag was then closed for about 5 minutes to allow the bag's head-

space to equilibrate with the volatile organic compounds (VOCs) in the soil. The PID probe was then inserted into the bag's head-space and the resultant PID reading was recorded.

The dimensions of the excavation pit necessary to remove the UST was approximately 6 feet in width by 19 feet in length.

#### 2. Note the depth of tank burial(s) (from land surface to top of tank).

The top of the UST was located 3 feet below land surface. The bottom of the tank was located at approximately 5 feet below lands surface. The tanks were resting on and surrounded by soil.

#### 3. Note volume of soil excavated.

Only soil necessary to remove the tank was excavated and stockpiled on polyethylene sheeting near the excavation pit and within the NCDOT right-of-way. The stockpiled soil (approximately 3.8 cubic meters) was covered with a polyethylene liner and contained on all sides with bails of straw.

#### 4. Describe soil type(s) encountered.

The soil encountered at the site was generally silty clay ranging in color from dark reddish brown to grayish brown, with minor amounts of silty sand.

#### 5. Describe type and source of backfill used.

At the request of the NCDOT the excavation pit was secured with barricade fencing and not backfilled.

#### 6. Describe condition of UST system(s) (i.e., pitting, holes, etc.).

The top of the UST was damaged. Small dents and cracks were observed.

### 7. Note if the excavation reached the groundwater table or bedrock surface.

Neither groundwater nor bedrock were encountered in the excavation pit.

#### E. Contaminated Soil

#### 1. Describe how it was determined to what extent to excavate the soil.

ARCADIS Geraghty & Miller guided the excavation activities by visually inspecting and screening soil samples with an OVM. Samples were screened by placing a portion of the sample into a resealable bag. The bag was then closed for about 5 minutes to allow the bag's headspace to equilibrate with the VOCs in the soil. The OVM probe was then inserted into the bag's headspace and the resultant OVM reading was recorded. Visual observations and screening by OVM indicated that no impacted soil was present in the bottom or side walls of the tank pits, after the tank was removed.

## 2. Describe method of temporary storage, sampling, and treatment/disposal of

Only soil necessary to remove the tank was excavated and stockpiled on polyethylene sheeting near the excavation pit and within the NCDOT right-of-way. The stockpiled soil

(approximately 3.8 cubic meters) was covered with a polyethylene liner and contained on all sides with bails of straw. One hand-augered soil boring was advanced within the stockpile. Three discrete sub-samples (SP-1A, SP-1B, SP-1C) were collected from three depths at each of the boring locations. Stockpile sub-samples were then packed into laboratory-provided sample containers, placed on ice in a cooler immediately after collection, and transported by ARCADIS Geraghty & Miller personnel directly to C&ET. A chain of custody record was provided with each cooler containing samples to maintain a record of personnel that had contact with the samples. A copy of the chain of custody is provided in Appendix E. The stockpile soil sub-samples were composited at C&ET into three composite samples and analyzed for high fraction hydrocarbons and low fraction hydrocarbons using USEPA Methods 3550 and 5030, respectively.

Analytical results indicated that low fraction hydrocarbons were not detected in concentrations which exceed reportable limits 0.10 mg/kg. However, the analytical results indicated high fraction hydrocarbons detected at a concentration of 68.5 mg/kg. A copy of the laboratory analytical results is provided in Appendix F. The excavated and stockpiled soil will be transported off-site by Soil Solutions, Inc. and is going to be treated by enhanced bioremediation at their facility.

#### III. Site Investigation

A. Provide information on field screening and physical observations, as well as methods used to calibrate field screening instrument(s).

ARCADIS Geraghty & Miller guided the excavation activities by visually inspecting and screening periodic soil samples with an OVM. OVM screening procedures were discussed in previous sections. The OVM was calibrated on at least a daily basis using a zero gas and a 100 part per million by volume (ppmv) isobutylene calibration gas.

- B. Describe soil sampling points and sampling procedures used.
  - 1. Samples Associated with Underground Storage Tanks.

A total of two grab samples were collected for laboratory analysis from the UST pit bottom directly below the UST after it was removed. Samples, labeled WA-1 and WA2, were collected from approximately 5 to 5.5 feet below land surface. samples were then packed into laboratory-provided sample containers, placed on ice in a cooler immediately after collection, and transported by ARCADIS Geraghty & Miller personnel directly to C&ET. A chain of custody record was provided with each cooler containing samples to maintain a record of personnel that had contact with the samples. A copy of the chain of custody is provided in Appendix E.

Soil samples were analyzed for high fraction hydrocarbons and low fraction hydrocarbons using USEPA Methods 3550 and 5030, respectively. Analytical results indicated that high and low fraction hydrocarbons were not detected in concentrations that exceed reportable limits of 10 mg/kg and 0.10 mg/kg, respectively. A copy of the laboratory analytical results is provided in Appendix F.

2. Samples Associated with Pipeline and Transfer Lines.

No samples were taken because no pipelines or transfer lines were present.

#### C. Describe groundwater or surface water sampling procedures

Groundwater or surface water samples were not collected during this investigation

#### D. Describe quality control measures

Stainless steel spoons were used to collect the soil samples directly from the backhoe bucket. Fresh latex gloves were worn while the soil was transferred from the sampling devices to the laboratory-supplied containers. Sampling equipment was decontaminated between each location with a clean water rinse, soapy water wash, followed by a clean water rinse.

The sample containers were labeled, placed in ice-filled coolers, and then remained in the custody of an ARCADIS Geraghty & Miller representative until delivery to C&ET in Cary, North Carolina.

Quality control samples were not collected during the UST closure activities.

#### E. Describe investigation results, including:

#### 1. Tank Removal Analytical Results

Constituents	WA-1	WA-2
High Fraction Hydrocarbons USEPA Method 3550 (mg/kg dw)	<10.0	<10.0
Low Fraction Hydrocarbons USEPA Method 5030 (mg/kg dw)	<0.10	<0.10

- 2. Pipeline Analytical Results N/A
- 3. Transfer Line Analytical Results
  N/A

#### IV. Conclusions and Recommendations

Field observations and analytical results indicate that a clean closure of this UST has been achieved. No further action should be required at this site.

### V. Signature and Seal of Professional Engineer or Licensed Geologist

William H. Doucette, Jr. Ph.D., L.G. Associate/Project Manager



VI. Enclosures

### **ARCADIS** GERAGHTY&MILLER

Underground Storage Tank Closure Assessment Report

APPENDIX D

LABORATORY ANALYTICAL DATA REPORTS

ENVIRONMENTAL ANALYTICAL SERVICES

JAN 2 1 1999

ARCADIL Centrality & Miller

FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC 2301 REXWOODS DRIVE SUITE 200

REPORT DATE: 01/19/99

RALEIGH, NC 27607-Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155081 SAMPLE ID- HG-1

DATE SAMPLED- 01/05/99

SAMPLE MATRIX- SO TIME SAMPLED- 1100 RECEIVED BY- THL

DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624 DELIVERED BY- C. WHITFIELD

Page 1 of 1

PROJECT NAME : NC DOT/GRNSBRO

		SAMPLE F	REP	ANALYSIS				
ANALYSIS	METHOD	DATE	BY	DATE	BY	RESULT	UNITS	PQL
PERCENT SOLIDS	2540G			01/07/99	BWH	82.5	NA	
HIGH FRACTION HYDROCARBON/COMB	3550	01/18/99	) AEK	01/18/99	JBR	< 10.0	mg/kg	10.0
LOW FRACTION HYDROCARBON/COMB	5030			01/14/99	JBR	< 0.10	mg/kg	0.10

PQL = Practical Quantitation Limit Results followed by the letter J are estimated concentrations. All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section. Wet Weight Concentration = (dry weight conc.) (percent solids)/100.

NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR Jemes Letynberger

ENVIRONMENTAL ANALYTICAL SERVICES

RÉPORT DATE: 01/19/99

FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC 2301 REXWOODS DRIVE SUITE 200

RALEIGH, NC 27607-

Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155082 SAMPLE ID- HG-2

LOW FRACTION HYDROCARBON/COMB 5030

DATE SAMPLED- 01/05/99

DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624 DELIVERED BY- C. WHITFIELD

Page 1 of 1

PROJECT NAME : NC DOT/GRNSBRO

SAMPLE PREP ANALYSIS ANALYSIS DATE BY DATE BY RESULT UNITS PQL METHOD PERCENT SOLIDS 01/07/99 BWH 83.1 NA 2540G 01/18/99 AEK 01/18/99 JBR < 10.0 mg/kg HIGH FRACTION HYDROCARBON/COMB 3550 10.0 01/14/99 JBR < 0.10 mg/kg 0.10

PQL = Practical Quantitation Limit Results followed by the letter J are estimated concentrations.

All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section. Wet Weight Concentration = (dry weight conc.) (percent solids)/100.

NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR Juli Klyberger

SAMPLE MATRIX- SO

RECEIVED BY- THL

TIME SAMPLED- 1100

ENVIRONMENTAL ANALYTICAL SERVICES

FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC 2301 REXWOODS DRIVE

REPORT DATE: 01/19/99

SUITE 200

RALEIGH, NC 27607-Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155083 SAMPLE ID- WA-1

DATE SAMPLED- 01/05/99

SAMPLE MATRIX- SO TIME SAMPLED- 1200

DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624 DELIVERED BY- C. WHITFIELD

RECEIVED BY- THL

Page 1 of 1

PROJECT NAME : NC DOT/GRNSBRO

		SAMPLE PREI	ANALYSIS		
ANALYSIS	METHOD	DATE I	Y DATE BY	RESULT UNITS	PQL
		1			
PERCENT SOLIDS	2540G	l	01/07/99 BW	AN E.E8 H	
HIGH FRACTION HYDROCARBON/COMB	3550	01/18/99 AI	K 01/18/99 JB	R < 10.0 mg/kg	10.0
LOW FRACTION HYDROCARBON/COMB	5030	1	01/14/99 JB	R < 0.10 mg/kg	0.10

PQL = Practical Quantitation Limit

Results followed by the letter J are estimated concentrations.

All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section. Wet Weight Concentration = (dry weight conc.) (percent solids)/100.

NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR AMIL Lighterer

ENVIRONMENTAL ANALYTICAL SERVICES

#### FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC 2301 REXWOODS DRIVE SUITE 200

REPORT DATE: 01/19/99

RALEIGH, NC 27607-Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155084 SAMPLE ID- WA-2

DATE SAMPLED- 01/05/99

SAMPLE MATRIX- SO TIME SAMPLED- 1200 RECEIVED BY- THL

DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624 DELIVERED BY- C. WHITFIELD

Page 1 of 1

PROJECT NAME : NC DOT/GRNSBRO

ANALYSIS	METHOD	SAMPLE F		ANALYSIS DATE	BY	RESULT	UNITS	PQL
PERCENT SOLIDS	2540G			01/07/99	BWH	83.1	NA	
HIGH FRACTION HYDROCARBON/COMB	3550	01/18/99	) AEK	01/18/99	JBR	< 10.0	mg/kg	10.C
LOW FRACTION HYDROCARBON/COMB	5030	:		01/14/99	JBR	< 0.10	mg/kg	0.10

PQL = Practical Quantitation Limit Results followed by the letter J are estimated concentrations. All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section. Wet Weight Concentration = (dry weight conc.) (percent solids)/100.

NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR 21111 Ltycheral

ENVIRONMENTAL ANALYTICAL SERVICES

FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC 2301 REXWOODS DRIVE SUITE 200

REPORT DATE: 01/19/99

RALEIGH, NC 27607-Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155085 SAMPLE ID- GS-1

DATE SAMPLED- 01/05/99

DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624 DELIVERED BY- C. WHITFIELD

Page 1 of 1

PROJECT NAME : NC DOT/GRNSBRO

SAMPLE PREP ANALYSIS

DATE BY DATE BY RESULT UNITS PQL ANALYSIS METHOD

01/07/99 BWH 72.1 NA 2540G PERCENT SOLIDS

HIGH FRACTION HYDROCARBON/COMB 3550 01/18/99 AEK 01/18/99 JBR < 10.0 mg/kg 10.0 0.10

LOW FRACTION HYDROCARBON/COMB 5030

01/14/99 JBR < 0.10 mg/kg

SAMPLE MATRIX- SO

RECEIVED BY- THL

TIME SAMPLED- 1325

PQL = Practical Quantitation Limit

Results followed by the letter J are estimated concentrations.

All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section. Wet Weight Concentration =

(dry weight conc.) (percent solids)/100.

NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR AMI Tetrenberge

ENVIRONMENTAL ANALYTICAL SERVICES

FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC 2301 REXWOODS DRIVE

SUITE 200

RALEIGH, NC 27607-

Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155086 SAMPLE ID- GS-2

DATE SAMPLED- 01/05/99

DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624 DELIVERED BY- C. WHITFIELD

SAMPLE MATRIX- SO TIME SAMPLED- 1325 RECEIVED BY- THL

PQL

Page 1 of 1

ANALYSIS

PROJECT NAME : NC DOT/GRNSBRO

SAMPLE PREP ANALYSIS DATE BY DATE BY RESULT UNITS METHOD

REPORT DATE: 01/19/99

PERCENT SOLIDS 2540G 01/07/99 BWH 72.6 NA

01/18/99 AEK 01/18/99 JBR < 10.0 mg/kg 10.0 HIGH FRACTION HYDROCARBON/COMB 3550 0.10

LOW FRACTION HYDROCARBON/COMB 5030 01/14/99 JBR < 0.10 mg/kg

PQL = Practical Quantitation Limit

Results followed by the letter J are estimated concentrations.

All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section. Wet Weight Concentration = (dry weight conc.) (percent solids) /100.

NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR Jani. Atyukinga

ENVIRONMENTAL ANALYTICAL SERVICES.

FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC

2301 REXWOODS DRIVE

REPORT DATE: 01/19/99

SUITE 200

RALEIGH, NC 27607-

Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155087 SAMPLE ID- SP-1

DATE SAMPLED- 01/05/99

TIME SAMPLED- 1430 RECEIVED BY- THL DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624 DELIVERED BY- C. WHITFIELD

Page 1 of 1

PROJECT NAME : NC DOT/GRNSBRO

ANALYSIS	METHOD	SAMPLE DATE	ANALYSIS DATE	BY	RESULT	UNITS	PQL
PERCENT SOLIDS HIGH FRACTION HYDROCARBON/COMB	2540G 3550	01/18/9	01/07/99	JBR		mg/kg	10.0
LOW FRACTION HYDROCARBON/COMB	5030		01/14/99	JBR	< 0.10	mg/kg	0.10

PQL = Practical Quantitation Limit Results followed by the letter J are estimated concentrations. All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section; Wet Weight Concentration = (dry weight conc.) (percent solids)/100.

HIGH FRACTION HYDROCARBON WAS IDENTIFIED AS FUEL OIL # 2. NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR July Litylubusger

SAMPLE MATRIX- SO

ENVIRONMENTAL ANALYTICAL SERVICES

FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC 2301 REXWOODS DRIVE SUITE 200

REPORT DATE: 01/19/99

RALEIGH, NC 27607-

Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155088 SAMPLE ID- SP-2

DATE SAMPLED- 01/05/99

SAMPLE MATRIX- SO TIME SAMPLED- 1445 RECEIVED BY- THL

DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624 DELIVERED BY- C. WHITFIELD

Page 1 of 1

PROJECT NAME : NC DOT/GRNSBRO

SAMPLE PREP ANALYSIS

PQL DATE BY DATE BY RESULT UNITS ANALYSIS METHOD

01/07/99 BWH 77.6 NA PERCENT SOLIDS 2540G

01/18/99 AEK 01/18/99 JBR < 10.0 mg/kg 10.0 HIGH FRACTION HYDROCARBON/COMB 3550 0.10

LOW FRACTION HYDROCARBON/COMB 5030

01/14/99 JBR < 0.10 mg/kg

PQL = Practical Quantitation Limit

Results followed by the letter J are estimated concentrations.

All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section. Wet Weight Concentration =

(dry weight conc.) (percent solids) / 100.

NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR Jevil Lityenherger

**FNVIRONMENTAL ANALYTICAL SERVICES** 

FINAL REPORT OF ANALYSES

ARCADIS-GERAGHTY & MILLER /NC

2301 REXWOODS DRIVE

SUITE 200 RALEIGH, NC 27607-

Attn: ROB ELLIS

NCDOT GREENSBORO #8.U492101

SAMPLE NUMBER- 155089 SAMPLE ID- SP-3

DATE SAMPLED- 01/05/99

DATE RECEIVED- 01/05/99 SAMPLER- CALVIN WHITFIELD

TIME RECEIVED- 1624

DELIVERED BY- C. WHITFIELD

Page 1 of 1

PROJECT NAME : NC DOT/GRNSBRO

SAMPLE PREP ANALYSIS

REPORT DATE: 01/19/99

PQL DATE BY DATE BY RESULT UNITS METHOD ANALYSIS

71.4 NA 01/07/99 BWH PERCENT SOLIDS 2540G

01/18/99 AEK 01/18/99 JBR < 10.0 mg/kg HIGH FRACTION HYDROCARBON/COMB 3550 01/14/99 JBR < 0.10 mg/kg

LOW FRACTION HYDROCARBON/COMB 5030

POL = Practical Quantitation Limit Results followed by the letter J are estimated concentrations.

All results for soil and sludge samples are reported on a dry weight basis as required by the NC DEM Laboratory Certification Section. Wet Weight Concentration =

(dry weight conc.) (percent solids)/100.

NC DENR CERTIFICATIONS: DWQ - 96; PUBLIC WATER SUPPLY - 37724

LABORATORY DIRECTOR AME Lity begge

SAMPLE MATRIX- SO

TIME SAMPLED- 1500

10.C

0.10

RECEIVED BY- THL

	Delivery Method: Mn Person ☐ Common Carrier ☐ Lab Courier	Special Instructions/Remarks: Composition SP-1A, 10, 10, 10, 10, 10, 10, 10, 10, 10, 10	Organization: Date/	Relinquished by: Organization: Date/	Received by: Strike Star berly Organization: CE Date 1/2	Organization: Afrans CTM Date 1/	Sample Matrix: L = Liquid; S = Solid; A = Air	4 4	SP-38 (-S-3) 1	SP-SA ) 150		34. 1 34. 1 2-85 582.45			SP-13(SP-1) 1/36 1			GC-1 1325 1	7		HG-2 1	C	Sample ID/Location Matrix Sampled Lab ID	Sampler(s)/Affiliation Course Whithard 1873		Laboratory CHONICAL & ENVIRONMENTAL PECH.		Project MullipelyMaille
--	---	---	---------------------	--------------------------------------	--	----------------------------------	---	-----	----------------	-------------	--	-------------------------	--	--	--------------------	--	--	-------------	---	--	--------	---	--	---	--	---	--	-------------------------

ENVIRONMENTAL ANALYTICAL SERVICES

#### **METHOD REFERENCES**

Federal Register, Vol. 59, 40 CFR Part 136.3, January 31, 1994

--Metals, Inorganics, and Organics for groundwater and wastewater

Federal Register, Vol. 56, 40 CFR Parts 141-143, January 30, 1991

--Metals, Inorganics, and Organics for drinking water

"Groundwater Section Guidelines for the Investigation and Remediation of Soils and Groundwater", NCDEHNR, DEM, March 1993.

--High Fraction Hydrocarbon and Low Fraction Hydrocarbon for groundwater and soil

SW-846, Third Edition, Revision I, July 1992

--Inorganics and Organics in soil or sludges. Metals in soil, sludge, or groundwater. (Metals in groundwater are digested by Method 3030C, Standard Methods, 18th Edition)

40 CFR Part 261, Appendix II and III

-- Toxic Characteristic Leaching Procedure

Standard Methods, 18th Edition, 1992

--Total and Fecal Coliform in wastewater, streams, and lakes